



555 Oak Street East
North Bay, Ontario
P1B 8L3

555, rue Oak Est
North Bay (Ontario)
P1B 8L3

Tel: 1-800-363-7512
www.ontarionorthland.ca

May 27, 2025

Addendum No. 01

File Reference Number: RFP 2025 035

Title: Iroquois Falls Subdivision Track Rehabilitation

RE: Clarifications/Questions

Please refer to the following information / clarifications:

Item 1: Will these 3000 tie plates from the price schedule be installed on the new ties?

Answer: The 3,000 tie plates from the price schedule will not be included with the new ties.

Item 2: What size of turnouts are being replaced?

Answer: The size of the turnouts being replaced are 90 lb., No.8.

Item 3: What size of turnouts are being installed?

Answer: The turnouts are being replaced with 115lb, No.8.

Item 4: What is the location of the turnouts, Is there road access to the turnouts?

Answer: All turnouts are located in Iroquois Falls rail yard.

Item 5: Are the turnouts pre-plated and pre-drilled?

Answer: Turnouts are not pre-plated and pre-drilled.

This Addendum hereby forms part of the RFP.

Regards,

Brinda Ranpura
Procurement Contracts Specialist
brinda.ranpura@ontarionorthland.ca